



Схема сборки

Стол двойной W2ST 127, W2ST 147, W2ST 167
W2CET 149.1, W2CET 149.2, W2CET 149.3,
W2CET 169.1, W2CET 169.2, W2CET 169.3




ВНИМАНИЕ!!!

При установке экранов кронштейн крепится к столешнице до ее монтажа к стенкам боковым и царге (см. схему сборки экрана).




Габаритные размеры:

W2ST 127 - 1200x1410x750 мм
W2ST 147 - 1400x1410x750 мм
W2ST 167 - 1600x1410x750 мм




Габаритные размеры:

W2CET 149.1 - 1400x1810x750 мм
W2CET 169.1 - 1600x1810x750 мм




Габаритные размеры:

W2CET 149.2 - 1400x1810x750 мм
W2CET 169.2 - 1600x1810x750 мм



Габаритные размеры:

W2CET 149.3 - 1400x1810x750 мм
W2CET 169.3 - 1600x1810x750 мм



ВНИМАНИЕ!!!

Предприятие-изготовитель оставляет за собой право вносить изменения в конструкцию и применять фурнитуру, отличающуюся от указанной в схеме сборки, но не ведущие к ухудшению качества и кардинальному изменению внешнего вида изделия.

Комплектация деталей:

- 1. Столешница 2шт
- 2. Стенка боковая 2шт
- 3. Царга 2шт

Комплектация фурнитуры:

а		18 шт.	е		6 шт.
б		18 шт.	ж		X2ST 4 шт.
в		18 шт.			X2CET 2 шт.
з		8 шт.	и		10 шт.
д		6 шт.			

Эман 1

Diagram showing the assembly of a long panel (3) to a vertical panel (2). The assembly is secured with screws (a) and dowels (z). An inset shows the assembly of a screw (a) and a dowel (z) into a pre-drilled hole.

Эман 2

Diagram showing the assembly of a top panel (2) to the side panels (3). The assembly is secured with screws (a) and dowels (z). An inset shows a screw (a) being inserted into a panel. A detailed view shows a screw (a) being inserted into a panel (2) using a screwdriver. A list of parts includes: a (x8), б (x8), д (x6), and e (x6).

Эман 3

Diagram showing the assembly of a bottom panel (2) to the side panels (3). The assembly is secured with screws (a) and dowels (z). An inset shows a screw (a) being inserted into a panel.

Эман 4

Diagram showing the assembly of a front panel (1) to the side panels (3). The assembly is secured with screws (б). An inset shows a screw (б) being inserted into a panel.

Эман 5

Diagram showing the assembly of a back panel (1) to the side panels (3). The assembly is secured with screws (б). An inset shows a screw (б) being inserted into a panel. A list of parts includes: б (x10).

Эман 6

Diagram showing the final assembly of the cabinet. The front and back panels (1) are attached to the side panels (3) and secured with screws (б). An inset shows a screw (б) being inserted into a panel. A list of parts includes: б (x18), д (x4), and e (x2).